

X  
**ROADWAY  
SERVICES, INC.**

1077 GORGE BOULEVARD  
P O BOX 88  
AKRON, OH 44309-0088  
(216) 384-8184



July 17, 1989

0310455034/Cook/  
Roadway  
Lust / Tech Report

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Illinois Environmental Protection Agency  
Division of Land Pollution Control  
Remedial Project Management Section  
Leaking Underground Storage Tank Unit  
2200 Churchill Road  
Post Office Box 19276  
Springfield, Illinois 62794-9276

Re: Cook/Chicago Heights - 891102  
Roadway Services, Inc.  
200 Lincoln Highway  
Compliance File

RECEIVED

JUL 7 1989

IEPA-DLPC

Dear Sir/Madam:

In response to your letter dated July 10, 1989, we submit the following information. Please correct your records with regard to the referenced leak occurrence which occurred in the engine oil piping system and not in the underground storage tank as mentioned in your letter.

1. The completed yellow copy of the contingency plan has been mailed to IEPA - ERV #29, 2200 Churchill Road, P.O. Box 19276, Springfield, IL 62794-9276.
2. Actions taken to control the situation and reduce the hazards on site:
  - a. Immediately the whole system was shut down and an investigation was conducted. A leak was located in the piping system. The system remained inoperative until the leak was fixed.
  - b. Immediately a visual inspection was performed. No above-ground or any exposed below-ground release was found.
  - c. As soon as a leak was suspected, the whole system was shut down. The piping system was isolated from the tank and the location of the leak was determined. Immediately the leaking pipe was uncovered and the excavated material was placed on the 4 millimeter Visqueen sheets. The leaking pipe was repaired.
  - d. Upon visual inspection, we did not find any evidence of any vapor or any free product entering into the sewers or subsurface structures.



- e. The excavated material was placed on Visqueen and it is kept covered by Visqueen.
3. There was no free product.
4. There were no noticeable inventory losses for the year prior to the discovery of the release.
5. The tank and piping system were tested tight in April, 1985.
6. Steps taken to determine the scope of the contamination and a timetable for remedial actions:

<u>Tasks</u>	<u>Timetable</u>
Leak location	6/29/89
Contaminated soil excavation	7/6/89
Soil samples sent to a lab	7/7/89
Soil sample results	7/20/89
Disposal permit application to Illinois Environmental Protection Agency (EPA)	7/21/89
Expected approval from Illinois EPA	8/14/89
Completion of the work	8/18/89

7. The following contractors' services have been secured to perform the clean-up and the analysis:


ICEP  
3468 Watling Road  
East Chicago, Indiana 46312  
219/397-5823  
Joseph Poracky

Tenco Laboratories  
1150 Junction Avenue  
Schererville, Indiana 46375  
219/322-2560  
Gretchen Rubie

Should you have any questions or require further information, please do not hesitate to contact me at 216/384-2324.

Very truly yours,

Roadway Services, Inc. for  
Roadway Express, Inc.

  
R. Vijayvargiya, P.E.  
Environmental Engineer

jmc  
cc: Messrs. J. L. Mihelick  
M. T. Baumgardner